



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC

*Airport Ruzyne, 160 08 Prague 6  
Tel: 420 2 33320922, fax: 420 2 20562270*

## AIRWORTHINESS DIRECTIVE

**Number: CAA-AD-008/2003**

Date of issue: January 10, 2003

**AIRBUS**

A310, A300-600

---

### AIRCRAFT - RAM AIR TURBINE (ATA 29) - INSPECTION

---

**Applicability:** AIRBUS A310 and A300-600 aircraft, all certified models and all serial numbers on which AIRBUS production modification No. 12259 has been embodied (AIRBUS Service Bulletin (SB) A310-29-2086 or A300-29-6048 in service).

**Effective date:** February 20, 2003

**Compliance:** Required as indicated DGAC AD 2002-638(B).

---

*Remarks: The compliance of this AD must be recorded in Aircraft Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel.: 420 2 33320922, fax: 420 2 20562270.*

**Ing. Pavel MATOUŠEK**  
**Director of Airworthiness Division**  
**CAA CZ**

## **DGAC AD No.: 2002-638(B)**

### **AIRBUS**

#### **A310 and A300-600 aircraft**

Ram Air Turbine (RAT) ejection jack (ATA 29)

#### **1. APPLICABILITY:**

AIRBUS A310 and A300-600 aircraft, all certified models and all serial numbers on which AIRBUS production modification No. 12259 has been embodied (AIRBUS Service Bulletin (SB) A310-29-2086 or A300-29-6048 in service).

#### **2. REASONS:**

An operator reported a case of rupture of the housing of the RAT ejection jack.

Investigations revealed that this rupture had been caused by overpressure in the jack, due to an overfilling of hydraulic fluid.

The manufacturer HAMILTON SUNDSTRAND questioned its filling procedure and identified a batch of jacks likely to have been incorrectly filled.

Such a type of rupture could prevent the deployment and use of the RAT in an emergency condition.

#### **3. COMPLIANCE:**

Within 2,500 flight hours following the effective date of this AD, unless already accomplished, check the serial number of the RAT ejection jack installed on the aircraft, and apply the corrective measures if necessary, in accordance with SB A310-29-2088 or A300-29-6050 (HAMILTON SUNDSTRAND Vendor Service Bulletin (VSB) ERPS03/04EJ-29-2).

Any jack on which HAMILTON SUNDSTRAND VSB ERPS03/04EJ-29-2 has been applied must be marked with the date of application of the VSB, accompanied with symbol "29-2" in the "MOD AND DATE" zone of the identification plate.

#### **REF.:**

AIRBUS Service Bulletins:

A310-29-2086

A300-29-6048

A310-29-2088

A300-29-6050

(All later approved revisions of these SBs are acceptable)

HAMILTON SUNDSTRAND Vendor Service Bulletin ERPS03/04EJ-29-2.

**EFFECTIVE DATE: JANUARY 04, 2003**