



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC  
Airworthiness Division

*Airport Ruzyně, 160 08 Prague 6  
Tel: 420 2 33320922, fax: 420 2 20562270*

## AIRWORTHINESS DIRECTIVE

**Number: CAA-AD-061/2003**

Date of issue: July 17, 2003

**BOEING**

737-600, -700, -700C, -800, -900

757, 767

---

### APPLIANCE - OXYGEN MASKS - AFM REVISION

---

**Applicability:** All Model 737-600, 737-700, 737-700C, 737-800, 737-900, 757, and 767 series airplanes; certificated in any category.

**Effective date:** August 18, 2003

**Compliance:** Required as indicated FAA AD 2003-14-08.

---

*Remarks: The compliance of this AD must be recorded in Aircraft Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyně Airport, 160 08 Prague 6, Czech Republic, tel.: 420 2 33320922, fax: 420 2 20562270.*

**Ing. Pavel MATOUŠEK**  
Director

**2003-14-08 Boeing:** Amendment 39-13227. Docket 2002-NM-282-AD.

*Applicability:* All Model 737-600, 737-700, 737-700C, 737-800, 737-900, 757, and 767 series airplanes; certificated in any category.

**Note 1:** The requirements of this AD are similar to those in AD 2003-03-15, amendment 39-13039, which applies to various Boeing and McDonnell Douglas transport category airplanes.

*Compliance:* Required as indicated, unless accomplished previously.

To prevent incapacitation of the flightcrew due to lack of oxygen, which could result in loss of control of the airplane, accomplish the following:

**Revision to the Airplane Flight Manual**

(a) Within 90 days after the effective date of this AD: For the applicable airplane models listed in the "For--" column of Table 1 of this AD, revise the procedures regarding donning oxygen masks in the event of rapid depressurization, as contained in the Emergency Procedures or Non-Normal Procedures section of the Airplane Flight Manual (AFM), as applicable, by replacing the text in the "Replace--" column of Table 1 of this AD with the information in the applicable figure referenced in the "With the Information In--" column of Table 1 of this AD. This may be accomplished by recording the AD number of this AD on the applicable figure and inserting it into the AFM. Table 1 and Figures 1 through 3 follow:

Table 1.--AFM Revisions

<b>For-</b>	<b>Replace-</b>	<b>With the Information in-</b>
Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes.	" <i>Rapid Depressurization</i> (With airplane altitude above 14,000 feet M.S.L.). Oxygen Masks & Regulators—ON, 100%"	Figure 1 of this AD.
Boeing Model 757-200, -200PF, -200CB; and Boeing Model 767-200, -300, and -300F series airplanes.	" <i>Rapid Depressurization</i> Recall Oxygen Masks and Regulators-ON"	Figure 2 of this AD.
Boeing Model 757-300 series airplanes	"Rapid Depressurization Put on oxygen masks, and establish crew communications".	Figure 3 of this AD.
Boeing Model 767-400ER series airplanes	"Rapid Depressurization Turn on oxygen masks, and establish crew communications".	Figure 3 of this AD.

**Figure 1**

**For Boeing Model 737-600, -700, -700C, -800, and -900 Series Airplanes**

Insert the information in this figure into the "Non-Normal Procedures" section of the FAA-approved Airplane Flight Manual.

*"Cabin Altitude Warning or Rapid Depressurization*

Condition: The cabin altitude warning horn sounds:  
Oxygen Masks & Regulators ON, 100%"

The rest of the steps under this heading in the AFM are unchanged.

**Figure 2**

**For Boeing Model 757-200, -200PF, and -200CB; and Model 767-200, -300, and -300F Series Airplanes**

Insert the information in this figure into the "Emergency Procedures" section of the FAA-approved Airplane Flight Manual.

*"Cabin Altitude Warning or Rapid Depressurization*

Condition: The CABIN ALT or CABIN ALTITUDE light illuminated indicates cabin altitude is excessive:

RECALL

Oxygen Masks & Regulators ON, 100%"

The rest of the steps under this heading in the AFM are unchanged.

**Figure 3**

**For Boeing Model 757-300 and 767-400ER Series Airplanes**

Insert the information in this figure into the "Non-Normal Procedures" section of the FAA-approved Airplane Flight Manual.

*"Cabin Altitude Warning or Rapid Depressurization*

Condition: The CABIN ALT or CABIN ALTITUDE light illuminated indicates cabin altitude is excessive:

Put on oxygen masks and establish crew communications."

The rest of the steps under this heading in the AFM are unchanged.

**Alternative Methods of Compliance**

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Operations Inspector, who may add comments and then send it to the Manager, Seattle ACO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

**Special Flight Permits**

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Effective Date**

(d) This amendment becomes effective on August 18, 2003.

**Footer Information**

Issued in Renton, Washington, on July 7, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate,

Aircraft Certification Service.

[FR Doc. 03-17675 Filed 7-11-03; 8:45 am]

BILLING CODE 4910-13-P