



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC  
Airworthiness Division

Airport Ruzyne, 160 08 Prague 6  
tel: 420-233320922, fax: 420-220562270

## AIRWORTHINESS DIRECTIVE

**Number: CAA-AD-T-004/2001R1**

Supersedes CAA-AD-004/2001

Date of issue: May 26, 2003

**MORAVAN-AEROPLANES Inc.**  
Z-142C

---

### AIRCRAFT - LIMITATION OF OPERATION

---

**Applicability:** Applicable to Moravan-Aeroplanes Inc. made aircraft:  
Z-142C in case when the Mandatory Service Bulletin Z 142C/27a was performed.

**Reason:** If the aircraft is operated outside the CAA-FAA load spectrum limits (frequency of load factors), its safe life time 5500 TIS is changed. Based on the AMU1 Acceleration Registration Unit records, actual safe life time is determined. In this case it is not necessary to determined limitation of operation in Aerobatic or Utility category.

**Effective date:** Upon receipt.

**Compliance :**

For Z-142C S/N up to 0568 incl. in accordance with Mandatory Bulletin No. Z 142C/27a, which becomes herewith part of this AD and may be obtained from: MORAVAN - AEROPLANES a.s. Otrokovice, OTS Department, 765 81 Otrokovice, Czech Republic, tel.: +420-57-608-3940, fax.: +420-57-608-3009.

AMU1 Acceleration Registration Unit installation in accordance with Mandatory Bulletin Z 142C/20a stays in force.

For Z-142C S/N from 0569 incl. accomplished by the Manufacturer.

Z 142C-AMU1/2 Form with change of total safe life time must be inserted into Maintenance Manual of the Z 142C aircraft, Vol. I, Chapter 9.

---

Remarks: - The compliance of this AD must be recorded in Aircraft Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation

- Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division,  
Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel: 420 233320922, fax: 420 220562270.

**Ing. Pavel MATOUŠEK**  
Director