



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC  
Airworthiness Division  
Airport Ruzyně, 160 08 Prague 6  
Tel: 420 2 33320922, fax: 420 2 20562270

## AIRWORTHINESS DIRECTIVE

**Number: CAA-AD-T-062/1999R2**

Replaces CAA-AD-T-062/1999R1

Date of issue: August 05, 2004

**AIRBUS**

A310, A300-600

### AIRCRAFT - THRUST REVERSER - DIRECTIONAL PILOT VALVE - CANCELS AND REPLACES AD

---

**Applicability:** This Revision 2 cancels Airworthiness Directive (AD) CAA-AD-T-062/1999R1, which is replaced by AD 99-18-19 that is subject of cover CAA-AD-101/1999.

**Effective date:** September 30, 2004

---

*Remarks: The compliance of this AD must be recorded in Aircraft Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyně Airport, 160 08 Prague 6, Czech Republic, tel.: 420 2 33320922, fax: 420 2 20562270. This AD has been issued in accordance with F-1999-242-289 R2, which is approved under EASA reference No. 2004-7034.*

**Ing. Pavel MATOUŠEK**  
**Director**

**DGAC AD No.: F-1999-242-289 R2**

Airworthiness Directive(s) replaced: 1999-242-289 R1

**AIRBUS SAS**

**A310 and A300-600 aircraft**

Type certificate(s) No. 72, TCDS No 145

ATA 78

**Subject: Thrust reverser - Directional pilot valve**

**CANCELLATION NOTICE**

This Revision 2 cancels Airworthiness Directive (AD) 1999-242-289 which is replaced by AD 99-18-19 that is subject of cover AD 2002-362-IMP.

This AD revision is approved under reference EASA No 2004-7034 dated Juny 07, 2004.

**EFFECTIVE DATES:**

Original issue: Upon receipt of the telegraphic AD from June 07, 1999

Revision 1: February 14, 2004

Revision 2: July 17, 2004